



FR : vérifier le bon serrage de la visserie / boulonnerie avant utilisation.
NL : controleer de bevestiging van schroeven en moeren alvorens te gebruiken.

E : check the tightening of bolts and nuts before use.
D : kontrollieren Sie die Befestigung der Schrauben und Bolzen vor der Anwendung.



- A M8 **x6**
- B M8 **x6**
- C M8x20 **x6**
- D M8 **x6**
- E 034 **x6**

