

















































Q01  12x	Q02  1x	Q03  11x	Q04  1x
Q05  13x	Q07  2x	Q08  1x	Q09  1x
Q10  $\varnothing 22 \times 2 \times 1175 \text{ mm}$ 7x	Q11  $\varnothing 40 \times 750 \text{ mm}$ 4x	Q12  $\varnothing 6 \times 1 \times 900 \text{ mm}$ 6x	Q13  $\varnothing 6 \times 1 \times 1200 \text{ mm}$ 3x
Q14  $\varnothing 4 \times 40 \text{ mm}$ 6x	Q15  $\varnothing 6 \times 12 \text{ mm}$ 12x	Q18  13x	Q20  $\varnothing 22 \text{ mm}$ 7x
Q21  $\varnothing 40 \text{ mm}$ 4x	Q22  $\varnothing 15 \times 50 \text{ mm}$ 5x	Q23  $\varnothing 12 \text{ mm}$ 15x	Q24  M8 x 60 mm 15x
Q25  M10 x 20 mm 56x	Q28  M5 x 6 mm 13x	Q29  $\varnothing 5 \times 30 \text{ mm}$ 105x	Q32  $\varnothing 3.5 \times 25 \text{ mm}$ 30x


 Q33 M10 57x	 Q35 M5 DIN 562 13x	 Q36 M10 DIN9021 113x	 Q37 M8 DIN 125 14x	 Q38 M10 DIN 125 17x
 Q39a 1x	 Q39b 1x	 Q45 1x	 Q46 1x	 Q47 1x
 Q48 4x	 Q49 M10 x 8 mm 6x	 Q50 6x	 Q52 M10 x 35 mm 8x	 Q53 M6 x 16mm 12x
 Q54 M6 x 350mm 12x	 Q55 M6 DIN6334 25x	 Q56 14x	 Q57 M6 x 50mm 1x	 Q58 1x
 Q59 M6 DIN9021 13x	 Q60 100x100x2 mm 4x	 Q61 M6 4x	 Q62 M6 2x	 Q63 M6 x 35 mm 2x
 Q64 M6 x 90 mm 4x	 Q65 Ø 60 mm 3x	 Q66 Ø 51 x 985 mm 2x	 Q68 Ø 60 x 985 mm 1x	 S1 Q54 Q56 Q55 Q53 12x
 Q69 M14 DIN9021 1x	 Q70 M16 DIN9021 1x	 Q71 M6 DIN 125 6x		



5










12 mm






13 mm









17 mm




6




OPTION 1




7




12 mm



3,5 mm









17 mm




8 mm


OPTION 2





8



12 mm



3,5 mm





17 mm




8 mm


OPTION 3





V1 $H > 1840 \text{ mm}$






V2 $H \leq 1840 \text{ mm}$




V3 $H \leq 975 \text{ mm}$







10












12 mm







6 mm















8 mm








12





S18



S19

