



FR : vérifier le bon serrage de la visserie / boulonnerie avant utilisation.
NL : controleer de bevestiging van schroeven en moeren alvorens te gebruiken.

E : check the tightening of bolts and nuts before use.
D : kontrollieren Sie die Befestigung der Schrauben und Bolzen vor der Anwendung.



- A **M8**
x6
- B **M8**
x6
- C **M8x20**
x6
- D **M8**
x6
- E **034**
x6

