













































 <p>HS12</p> <p>8x</p>	 <p>HS13</p> <p>2x</p>	 <p>HS14</p> <p>2x</p>	 <p>ST20</p> <p>1x</p>	 <p>ST21</p> <p>M12</p> <p>1x</p>
 <p>ST22</p> <p>22x</p>	 <p>ST23a</p> <p>1x</p>	 <p>ST23b</p> <p>1x</p>	 <p>ST32</p> <p>12x</p>	 <p>ST35</p> <p>1x</p>
 <p>ST45</p> <p>10x</p>	 <p>ST46</p> <p>1x</p>	 <p>ST47</p> <p>1x</p>	 <p>GS09</p> <p><math>\varnothing 22 \times 2 \times 1175 \text{ mm}</math></p> <p>8x</p>	 <p>GS20</p> <p><math>\varnothing 22 \times 1 \times 1100 \text{ mm}</math></p> <p>3x</p>
 <p>KS01</p> <p><math>\varnothing 22 \text{ mm}</math></p> <p>8x</p>	 <p>KS05</p> <p><math>\varnothing 6 \times 12 \text{ mm}</math></p> <p>6x</p>	 <p>G06</p> <p><math>\varnothing 40 \times 952 \text{ mm}</math></p> <p>3x</p>	 <p>G10</p> <p>2x</p>	 <p>G11</p> <p>2x</p>
 <p>G16</p> <p><math>\varnothing 6 \times 1 \times 3000 \text{ mm}</math></p> <p>3x</p>	 <p>D01</p> <p>M8 x 55 mm</p> <p>14x</p>			
 <p>NT07</p> <p>4,2 x 19 mm</p> <p>6x</p>	 <p>NT09</p> <p><math>\varnothing 6 \times 30 \text{ mm}</math></p> <p>132x</p>	 <p>NT11</p> <p><math>\varnothing 4 \times 25 \text{ mm}</math></p> <p>22x</p>	 <p>NT18</p> <p>M10 x 20 mm</p> <p>4x</p>	 <p>NT20</p> <p>M8 x 70 mm</p> <p>14x</p>
 <p>NT22</p> <p>M10</p> <p>4x</p>	 <p>NT24</p> <p>M8</p> <p>12x</p>	 <p>NT25</p> <p>M10 DIN125A</p> <p>8x</p>	 <p>NT26</p> <p>M8 DIN125A</p> <p>14x</p>	 <p>NT29</p> <p>M12 x 120 mm</p> <p>1x</p>
 <p>NT30</p> <p>M5 x 6 mm</p> <p>17x</p>	 <p>NT31</p> <p>M5 DIN562</p> <p>17x</p>	 <p>NT32</p> <p>M10 x 8 mm</p> <p>54x</p>	 <p>NT34</p> <p>M12 DIN-9021</p> <p>1x</p>	 <p>NT35</p> <p>M8 x 80 mm</p> <p>12x</p>
 <p>NT37</p> <p>M8 DIN-9021</p> <p>12x</p>	 <p>NT38</p> <p>M12 DIN125A</p> <p>1x</p>			





3




12 mm







3,5 mm




13 mm




17 mm




4




6 mm







13 mm







12 mm




3,5 mm




5







6



12 mm



13 mm



3,5 mm

